

CLASS FM	DWG NO. 840917-TT 840918-TT
---------------------------	--

REVISIONS			
REV	DESCRIPTION	ENG	DATE
00	INITIAL RELEASE	LINDA XU	12/21

SIGNATURES REQUIRED		PRINT NAME	SIGNATURE
TSG REPRESENTATIVE		LINDA XU	
CELL LEAD		FRANK PUTIRKA	
REPAIR SUPERVISOR		CHARLES WOLFORD	

TSG ENGINEER LINDA XU	DATE 12/21	<i>BOSE</i> [®] FRAMINGHAM, MA 01701-9168
---------------------------------	----------------------	--

APPLICABLE DOCUMENTS: SERVICE MANUAL – 840917-SM, 840918-SM	DESCRIPTION Sub1, Sub2 (Grand Prix) Troubleshooting Tips				
	SIZE A	FSCM 32108	CLASS FM	DWG NO. 840917-TT, 840918-TT	REV 00

Description

Refer to the Sub1, Sub2 Powered Bass Module service manual, reference number 840917-SM (Sub1), 840918-SM (Sub2) located on the Professional Products / Live Music Technology Products page of the Bose Service web site for any information not presented in this document.

1. Preventative Repair Measures

Note: Perform the following on all units returned for repair.

Product	Check	Action
Sub1, Sub2	On all units that come in for repair / refurb.	Update firmware to the latest revision. Refer to the service manuals for update procedure.

2. Troubleshooting Tips

Product	Symptom	Action
Sub1, Sub2	Turn-on pop from second sub in SubMatch daisy-chain if first sub turned on last	Update firmware to the latest revision. Refer to the service manuals for update procedure.