



Release Notes

This software/firmware release includes the following changes.

DesignMax Pendant Loudspeakers

Addition of Loudspeaker EQs and SmartBass support for DesignMax DM3P, DM5P, DM6PE, DM10P-SUB

EdgeMax Preset Update

Resolves issues with $8\ \Omega$ configuration of EdgeMax EM90 and EM180: limiter now set to correct values of $63\ V^{\text{peak}}$, $31.5\ V^{\text{RMS}}$.

Supported Web Browsers

Google Chrome 89.0.4389.114 or later

Mozilla Firefox 87.0 or later

Microsoft Edge 89.0.774.75 or later

Known Issues, Defects & Limitations

The following are the known issues and defects with this release. Information included here can be useful when troubleshooting issues with software or hardware operation.

General Issues

If you have previously calibrated AutoVolume for a listening area and then choose to recalibrate it, the previous calibration will not be removed until Step 3 of the calibration process.

The Speaker EQ graph (under **Configuration > Outputs**) will not display BW36/BW48 for pre-defined loudspeakers, but these filters are being applied to the audio.

Backtracking in the Quick Setup Wizard Output configuration can cause channels to not show up as assignable. The current workaround is to exit and restart the Quick Setup Wizard.

The initial Dynamic EQ calibration level can be much louder than expected (0 dB). We recommend manually entering $-32\ \text{dB}$ into the initial calibration screen prior to making adjustments. Alternatively, refresh the browser immediately prior to calibrating Dynamic EQ.

AutoVolume metering does not display if AutoVolume is turned on by the ControlSpace Remote app or by a scheduled event. You must refresh the browser after AutoVolume is turned on to display the AutoVolume metering.

The Dashboard View does not automatically refresh to reflect changes made (e.g., source change). You must refresh the browser for the Dashboard to fully reflect current settings.

Discovery Tool Issues

If the PC being used to configure the CSP processor has a dual-NIC setup while on Wi-Fi and using a link-local direct connection, the Discovery Tool will be unable to identify the IP address of the CSP processor.

Browser-specific Issues

While using Microsoft Edge, the Quick Setup Wizard may not show some options (Stereo, Phantom) as available when configuring inputs. The current workaround is to advance the Wizard past the current Input and then click **Back**.

While using Internet Explorer, if a web browser is already connected to a CSP processor and another attempt is made to connect to the same processor, the **Starting CSP Configuration Utility** screen will appear instead of the **Multiple Browsers Connected** error screen.