



General

These release notes address the notable changes and information about the ControlSpace Remote software release, version 2.10.1. This information is current as of January 3, 2022.

For additional information regarding the ControlSpace Remote software see:
pro.bose.com/en_us/products/software/software_control/controlspace_remote.html

Questions and feedback related to the use and application of ControlSpace systems can be found at the Bose Professional Pro Audio community forum: community.bose.com/t5/Professional-Installed/bd-p/proaudio

New Features / Improvements

This release includes the following changes:

Reduction in meter data requests

- Meter data is now requested for the active page only. Once a page becomes active meter data is requested and displayed.

Fixes

There are no fixes within this release.

Known Issues, Defects and Limitations

The following are the known issues and defects with this release. Information included here can be useful when troubleshooting issues with software or hardware operation:



Minimum System Requirements

The following are the minimum system requirements for running ControlSpace Remote software applications:

Application	Platform				
	Windows (download)	macOS (download)	iOS (App Store only)	Android (download & Google Play store)	Android (64-bit) (download & Google Play store)
ControlSpace Remote Builder	Microsoft Windows 10 (32-bit or 64-bit)	n/a	n/a	n/a	n/a
ControlSpace Remote Admin	Microsoft Windows 10 (32-bit or 64-bit)	10.13 (High Sierra) 10.14 (Mojave) 10.15 (Catalina)	n/a	n/a	n/a
ControlSpace Remote Client	Microsoft Windows 10 (32-bit or 64-bit)	10.13 (High Sierra) 10.14 (Mojave) 10.15 (Catalina)	iOS 12 or newer	Android 6 (Marshmallow) or newer	Android 6 (Marshmallow) or newer